

INCIDENT ALERT

LOCATION: AGGREGATE DREDGER
ACTIVITY: ACCESS & EGRESS & WORKING AT HEIGHT
SUB ACTIVITY: N/A

ALERT STATUS: Normal
DATE ISSUED: 03/12/2020 12:28:45
INCIDENT No: 03577

TITLE

Operator sustains grazed/bruised back from contact with scaffolding -non-treatment injury - BMAPA Alert

COUNTRY OF ORIGIN

ACCIDENT / INCIDENT DETAILS

A UK marine aggregate dredger was undergoing its annual dry dock. Scaffolding had been erected in the vicinity of the aft screening tower to facilitate its removal. The scaffolding was erected across the starboard side walkway which restricted the walkway, with the scaffolding platform only being 1.5m above the spillway. The erected scaffolding had red and white hazard tape applied to highlight the low height of the scaffolding and the protruding scaffolding clips whilst waiting on delivery of protective foam.

The IP transited this walkway for general access to the engine room and in doing so, whilst crouched down, impacted his back on the protruding scaffolding clips. This caused a small abrasion and bruise on the left side under the shoulder.

It has been identified that there was inattention to immediate surroundings as the scaffolding was highlighted with hazard tape.

ACCIDENT / INCIDENT IMAGES

Click image to enlarge



LEARNING POINTS / ACTIONS TAKEN

- Staff to discuss the importance of paying attention to their immediate surroundings and the importance of making informed decisions where normal access routes may be restricted during maintenance periods.
- Ensure scaffolding has been fully completed, including foam protection fitted before signed off and used as a thoroughfare.

LEARNING POINTS / ACTIONS IMAGES