

**Re enactment:  
The HOBO fell under  
gravity after fitter  
slipped and initially  
grabbed it, resulting in  
the pinning of the fitters  
leg between the HOBO  
and the carousel**

